22,25

INLET

Rockford Sanitary Systems, Inc. ROCKFORD, IL 61125-0963

(815) 229-5077 - (800) 747-5077 - FAX (815) 229-5108 WEB SITE-www.rkfdseparators.com E MAIL-rssem@inwave.com

MODEL NO. GOST-5633-100

DIL/SAND SEPARATOR

DRAWN BY JOB NAME QUOTE # W.R.W. OPTIONAL FEATURES (ADDITIONAL COST) **VENT** ☐ ANCHOR FLANGE ☐ FILTER MEDIUM 25,50 □ RECESSED LIFT HANDLES IN COVERS VENT ☐ EPOXY COATING ☐ ANODES REINFORCED COVERS LOAD 9.38 9,38 □STAINLESS STEEL CONSTRUCTION ⊐SEDIMENT BASKET ☐ INTEGRAL EXTENSION _ □INLET & DUTLET SIZE _____INCHES □ DOUBLE WALL CONSTRUCTION □LEAK DETECTION INLET HIGH LEVEL SENSOR & ALARM COALESCING PACK ON DUTLET ☐ PUMP OUT CONNECTION 32.50 ☐ HOLD DOWN PADS ☐ DRY INLET 9,38 9,38 ⊐ALUMINUM C□VER □NO HUB CONNECTION VENT 25,50 ☐ HUB CONNECTION **VENT** - 69,87 -- 65,00 -56,25 21.75 9.50 \bigcirc 13,75 VENT VENT 36.00 30.00 26.50

Specifications

DUTLET

Rockford Model GOST-5633-100 Sand/Dil/Water Separator all welded A36 1/4" steel, 65 g.p.m. intermittent flow, 100 gallon static capacity with 100 gallon waste oil storage and 100 gallon sand interceptor, 4.00" threaded inlet/outlet & 4.00" threaded vent connections (4), visible double-wall outside trap seal, removable filter screen, non-removable separator screens, 3/8" nonskid treadplate covers (4) (for flush-with-floor installation) for pedestrian traffic secured with stainless steel bolts with heavy duty leakproof gasket, OPEX SHOP COAT coating inside & bituminous coating outside.

Optional features (Additional cost) listed above

Approved By	Company	Date