## Rockford Sanitary Systems, Inc. ROCKFORD, IL 61125-0963

(815) 229-5077 - (800) 747-5077 - FAX (815) 229-5108 WEB SITE-www.rkfdseparators.com E MAIL-rssem@rkfdseparators.com

MODEL NO.

OSL-5658

DIL/WATER SEPARATOR

DRAWN BY JOB NAME QUOTE # W.R.W. OPTIONAL FEATURES (ADDITIONAL COST) ☐ ANCHOR FLANGE RECESSED LIFT HANDLES\_\_\_\_PER COVER 45.38 □EPOXY COATING
□LIGHT TRAFFIC REINFORCED COVERS
□HEAVY TRAFFIC REINFORCED COVERS STAINLESS STEEL CONSTRUCTION DUTLET SEDIMENT BASKET INLET ☐ INTEGRAL EXTENSION \_\_ ☐ INLET & DUTLET SIZE \_ \_\_\_ INCHES DOUBLE WALL CONSTRUCTION ☐ LEAK DETECTION 22.50 ☐ FILTER MEDIUM COALESCING PACK ☐ ANDDES ☐ H□LD D□WN PADS 7.38 -7.38 □ ALUMINUM C□VER ☐ N□ HUB C□NNECTI□N **VENT VENT** ☐ HUB CONNECTION 95,38 - 45,00 -76.25 -33,50 -16.50 **VENT** 23.00  $\bigcirc$ DRAW OFF 60.00 48.00 43.50 37.00 31.00 INLET DUTLET

## Specifications

Rockford Model OSL-5658 Dil/Water Separator all welded 10 ga steel, 350 g.p.m. intermittent flow, 525 gallon static capacity, 6.00" Flanged inlet and outlet, 4.00" threaded vent connections (2), 3.00" oil draw-off connection, visible doublewall outside trap seal, removable filter screen, non-removable separator plates, 3/16" nonskid diamond tread-plate cover (for flush-with-floor installation) for pedestrian traffic secured with stainless steel bolts with heavy duty leakproof gasket, OPEX SHOP COAT coating inside & bituminous coating outside.

Optional features (Additional cost) listed above

		(R
Approved By	Company	Date