Rockford Sanitary Systems, Inc. ROCKFORD, IL 61125-0963

(815) 229-5077 - (800) 747-5077 - FAX (815) 229-5108 WEB SITE-www.rkfdseparators.com E MAIL-rssem@rkfdseparators.com

MODEL NO.

OSL - 5662

DIL/WATER SEPARATOR

DRAWN BY JOB NAME QUOTE # W.R.W. OPTIONAL FEATURES (ADDITIONAL COST) ☐ ANCHOR FLANGE RECESSED LIFT HANDLES PER COVER 49,38 -☐ EPOXY COATING ☐ LIGHT TRAFFIC REINFORCED COVERS☐ HEAVY TRAFFIC REINFORCED COVERS☐ STAINLESS STEEL CONSTRUCTION DUTLET ☐ SEDIMENT BASKET INLET ☐ INTEGRAL EXTENSION _ _INCHES ☐ INLET & DUTLET SIZE _ ☐ DOUBLE WALL CONSTRUCTION ☐ LEAK DETECTION 22.50 ☐ FILTER MEDIUM □ C□ALESCING PACK ☐ AN□DES THOLD DOWN PADS 13,38 --13,38 ☐ ALUMINUM COVER ☐ N□ HUB C□NNECTI□N **VENT** VENT ☐ HUB CONNECTION - 102,00 **-**45.00 83.00 -33,43 VENT 17.00 23,25 0 0 DRAW OFF 60.00 49.00 43.00 36,75 30.00 **INLET** DUTLET

Specifications

Rockford Model OSL-5662 Dil/Water Separator all welded A36 10ga. steel, 400 g.p.m. intermittent flow, 598 gallon static capacity, 6.00" Flanged inlet and outlet, 4.00" threaded vent connections (2), 3.00" oil draw-off connection, visible doublewall outside trap seal, removable filter screen, non-removable separator plates, 3/16" nonskid diamond treadplate cover (for flush-with-floor installation) for pedestrian traffic secured with stainless steel bolts with heavy duty leakproof gasket, OPEX SHOP COAT coating inside & bituminous coating outside.

Intional features (Additional cost) listed above

		VE 5. 3.10 5 V E
Approved By	Company	Date