## Rockford Sanitary Systems, Inc. ROCKFORD, IL 61125-0963


(815) 229-5077 - (800) 747-5077 - FAX (815) 229-5108 WEB SITE-www.rkfdseparators.com E MAIL-rssem@rkfdseparators.com

MODEL NO. OSTL-5628-50


DIL/WATER SEPARATOR


DRAWN BY QUOTE # W.R.W.

JOB NAME



OPTIONAL FEATURES (ADDITIONAL COST) ☐ ANCHOR FLANGE ☐ FILTER MEDIUM RECESSED LIFT HANDLES IN COVERS ☐ EPOXY COATING ☐ ANODES REINFORCED COVERS ☐ STAINLESS STEEL CONSTRUCTION ⊐SEDIMENT BASKET □ INTEGRAL EXTENSION \_\_\_\_\_INCHES □INLET & OUTLET SIZE\_ DOUBLE WALL CONSTRUCTION LEAK DETECTION ☐ HIGH LEVEL SENSOR & ALARM COALESCING PACK PUMP DUT CONNECTION





## Specifications

Rockford Model OSTL-5628-50 Dil/Water Separator all welded A36 10 ga steel, 35 g.p.m. intermittent flow, 64 gallon static capacity with 50 gallon waste oil storage, 3.00" threaded inlet/outlet & 3.00" threaded vent connections (4), visible double-wall outside trap seal, removable filter screen, non-removable separator screens, 3/16" nonskid tread-plate covers (2) (for flush-with-floor installation) for pedestrian traffic secured with stainless steel bolts with heavy duty leakproof gasket, OPEX SHOP COAT coating inside & bituminous coating outside.

Optional features (Additional cost) listed above

Approved	Ву
1 1PP1 0 4 C 01	~ ~