
## Rockford Sanitary Systems, Inc. ROCKFORD, IL 61125-0963

(815) 229-5077 - (800) 747-5077 - FAX (815) 229-5108 WEB SITE-www.rkfdseparators.com E MAIL-rssem@rkfdseparators.com

MODEL NO OSTL-5630-100


DIL/WATER SEPARATOR


DRAWN BY QUOTE # JOB NAME W.R.W.



OPTIONAL FEATURES (ADDITIONAL COST) ☐ ANCHOR FLANGE ☐ FILTER MEDIUM RECESSED LIFT HANDLES IN COVERS ☐ EPOXY COATING ☐ ANODES REINFORCED COVERS ISTAINLESS STEEL CONSTRUCTION SEDIMENT BASKET ☐ INTEGRAL EXTENSION \_ ☐ INLET & DUTLET SIZE \_ \_ INCHES DOUBLE WALL CONSTRUCTION ☐ LEAK DETECTION ☐ HIGH LEVEL SENSOR & ALARM □ C□ALESCING PACK PUMP DUT CONNECTION

HOLD DOWN PARS ⊒HOLD DOWN PADS ☐ STORAGE COMPARTMENT LADDER ☐ ALUMINUM COVER ☐ N☐ HUB C☐NNECTION ☐ HUB CONNECTION





## Specifications

Rockford Model 🗆 STL-5630-100 🗀 il/Water Separator all welded 10ga HR steel, 50 g.p.m. intermittent flow, 75 gallon static capacity with 100 gallon waste oil storage, 3.00" threaded inlet/outlet & 3.00" threaded vent connections (4), visible double-wall outside trap seal, removable filter screen, non-removable separator screens, 3/16" nonskid treadplate covers (2) (for flush-with-floor installation) for pedestrian traffic secured with stainless steel bolts with heavy duty leakproof gasket, OPEX SHOP COAT coating inside & bituminous coating outside.

Optional features (Additional cost) listed above

,		
Approved By	Company	Date